

Galveston County - District Court Administration Office

Audio-Visual System Assessment
600 59th St # 2305, Galveston, TX 77551



CourtRoom JAR EQUIPMENT LIST

#	Brand	Model #	Serial #	Description
1	Panasonic	PTRW330U	DE6210133	LED/ Laser 1-chip DLP, 3500 lumens, WXGA
2	Panasonic	PTRW330U	DE6210179	LED/ Laser 1-chip DLP, 3500 lumens, WXGA
3	Speakers (Qty 24)	N/A	N/A	70V Commercial Ceiling Speaker
4	Sharp	LC-80LE6500	A502848635	80" Class Aquos Hd Series Led Smart Tv
5	Sharp	LC-80LE6500	A502848627	80" Class Aquos Hd Series Led Smart Tv
6	Deuce mc	2220	QAAZ0050336	Video Encoder
7	Crestron	CNXRMC	6001320 1835747	Video Receiver and Control Interface
8	Mackie	402VL24	NA	4-channel Compact Analog Mixer
9	Shure	MX418D/C	N/A	Microflex® Standard Gooseneck Microphone
10	Apple	MC769LL/A	F5XKQILNDFHW	Apple iPad 2 MC769LL/A Tablet
11	Extron	TLM 100T	N/A	Secure Mounting Enclosure for iPad
12	Extron	CPM103	N/A	Three-Gang AV Connectivity Mounting Frame
13	Extron	CPM103	N/A	Three-Gang AV Connectivity Mounting Frame
14	Extron	CPM104	N/A	Three-Gang AV Connectivity Mounting Frame
15	Sennheiser	EM100G4	4439029703	Evolution G4 Wireless 100 Series True Diversity Receiver with Wireless Transmitter - A Band (516-558MHz)
16	Shure (Qty 3)	MX418D/C	N/A	Microflex® Standard Gooseneck Microphone
17	Apple	MC769LL/A	F5XKQILNDFHW	Apple iPad 2 MC769LL/A Tablet
18	Extron	TLM 100T	N/A	Secure Mounting Enclosure for iPad
19	Extron	CPM104	N/A	Three-Gang AV Connectivity Mounting Frame
20	Crestron	TPMC-CH-IMC	6002771 1687857	Balanced AV Interface Module for TPS--12

VISUAL INSPECTION

#	Brand	Model #	Serial #	Description
1	Panasonic	PTRW330U	DE6210133	Visible water damage in/around the component
2	Panasonic	PTRW330U	DE6210179	Visible water damage in/around the component
3	Speakers (Qty 24)	N/A	N/A	Visible water damage in/around the component
4	Sharp	LC-80LE6500	A502848635	Visible water damage in/around the component
5	Sharp	LC-80LE6500	A502848627	Visible water damage in/around the component
6	Deuce mc	2220	QAAZ0050336	Visible water damage in/around the component
7	Crestron	CNXRMC	6001320 1835747	Visible water damage in/around the component
8	Mackie	402VL24	NA	Visible water damage in/around the component
9	Shure	MX418D/C	N/A	Visible water damage in/around the component
10	Apple	MC769LL/A	F5XKQILNDFHW	Visible water damage in/around the component
11	Extron	TLM 100T	N/A	Visible water damage in/around the component
12	Extron	CPM103	N/A	Visible water damage in/around the component
13	Extron	CPM103	N/A	Visible water damage in/around the component
14	Extron	CPM104	N/A	Visible water damage in/around the component
15	Sennheiser	EM100G4	4439029703	Visible water damage in/around the component
16	Shure (Qty 3)	MX418D/C	N/A	Visible water damage in/around the component
17	Apple	MC769LL/A	F5XKQILNDFHW	Visible water damage in/around the component
18	Extron	TLM 100T	N/A	Visible water damage in/around the component
19	Extron	CPM104	N/A	Visible water damage in/around the component
20	Crestron	TPMC-CH-IMC	6002771 1687857	Visible water damage in/around the component

PERFORMANCE

#	Brand	Model #	Status	Description	Recommendation
1	Panasonic	PTRW330U	Operational	Unit working during inspection	Replace
2	Panasonic	PTRW330U	Operational	Unit working during inspection	Replace
3	Speakers (Qty 24)	N/A	Operational	Unit working during inspection	Replace
4	Sharp	LC-80LE6500	Operational	Unit working during inspection	Replace
5	Sharp	LC-80LE6500	Operational	Unit working during inspection	Replace
6	Deuce mc	2220	Operational	Unit working during inspection	Replace
7	Crestron	CNXRMC	Operational	Unit working during inspection	Replace
8	Mackie	402VL24	Operational	Unit working during inspection	Replace
9	Shure	MX418D/C	Operational	Unit working during inspection	Replace
10	Apple	MC769LL/A	Operational	Unit working during inspection	Replace
11	Extron	TLM 100T	Operational	Unit working during inspection	Replace
12	Extron	CPM103	Operational	Water Damage / Rusty	Replace
13	Extron	CPM103	Operational	Water Damage / Rusty	Replace
14	Extron	CPM104	Operational	Water Damage / Rusty	Replace
15	Sennheiser	EM100G4	Operational	Unit working during inspection	Replace
16	Shure (Qty 3)	MX418D/C	Operational	Unit working during inspection	Replace
17	Apple	MC769LL/A	Operational	Unit working during inspection	Replace
18	Extron	TLM 100T	Operational	Unit working during inspection	Replace
19	Extron	CPM104	Operational	Unit working during inspection	Replace
20	Crestron	TPMC-CH-IMC	Operational	Unit working during inspection	Replace

CourtRoom 1A & B Rack				EQUIPMENT LIST	
#	Brand	Model #	Serial #	Description	
1	Extron	MSW 4V	924539004 E14121	Four Input Composite Video Switcher	
2	Extron	MSW 4V	924539019 E14121	Four Input Composite Video Switcher	
3	Extron	DA 6V EQ	924582080 E15167	Six Output Composite Video Distribution Amplifier with Gain and EQ Controls	
4	Creston	AV2	6001376 1766591	Economical Dual Bus Control System	
5	Sennheiser	SI 1015	105949	Wideband Modulator	
6	Sennheiser	SI 1015	105818	Wideband Modulator	
7	Extron	SW6 RGBHV A	891160024 E15803	Six-Input RGBHV Switcher	
8	Extron	SW6 RGBHV A	909043021 E15251	Six-Input RGBHV Switcher	
9	Extron	DA6 RGBHV	913964020 E15712	Six Output Wideband RGBHV Distribution Amplifier	
10	Extron	DA6 RGBHV	913964002 E15712	Six Output Wideband RGBHV Distribution Amplifier	
11	Extron	DA4 RGBHV	916805028 E15749	Four Output Wideband RGBHV distribution Amplifier	
12	Surgex	SX2120	785550	Rackmountable 20-amp Surge Suppressor/Power Conditioner with 15 Outlets	
13	Apple	A1392	N/A	AirPort Express 802.11n (2nd Generation)	
14	Tyco	10012 AC-2A	N/A	Paging System	
15	Middle Atlantic	4715MS-12T-B10	N/A	Rackmount Fan Assembly with Two Cooling Fans	
16	Symnet	BREAKIN12	800IN122B0018	DSP Digital Signal Processor	
17	Symnet	8X8 DSP	800X686A0257	DSP Digital Signal Processor	
18	Symnet	8X8 DSP	800X885A0241	DSP Digital Signal Processor	
19	Symnet	8X8 DSP	8008X886A0256	DSP Digital Signal Processor	
20	QSC	CX108V	110550151	8-Channel 70V Power Amplifier	
21	QSC	CX108V	110550155	8-Channel 70V Power Amplifier	
22	Shure	SCM820	201117234	Digital IntelliMix Automatic Mixer	
23	Middle Atlantic (Qty 2)	PD-1415C-NS	NA	15A Corded Vertical Power Strip	
24	Middle Atlantic	MRK-4431	NA	MRK Series Rack, 44 RU, 31" D	
25	Middle Atlantic	MW-10 FT-FC	NA	10" Fan Mount with Fan Control	
26	Creston	C2N-HBLOCK	6001923 1269655	Multi-type Cresnet Distribution Block	
27	Symnet	8X8 DSP	8008X886A0264	DSP Digital Signal Processor	
28	RDL	FP-MX4	NA	Four-Channel Microphone and Line Audio Mixer	

VISUAL INSPECTION

#	Brand	Model #	Serial #	Description	
1	Extron	MSW 4V	924539004 E14121	Visible water damage in/around the component	
2	Extron	MSW 4V	924539019 E14121	Visible water damage in/around the component	
3	Extron	DA 6V EQ	924582080 E15167	Visible water damage in/around the component	
4	Creston	AV2	6001376 1766591	Visible water damage in/around the component	
5	Sennheiser	SI 1015	105949	Visible water damage in/around the component	
6	Sennheiser	SI 1015	105818	Visible water damage in/around the component	
7	Extron	SW6 RGBHV A	891160024 E15803	Visible water damage in/around the component	
8	Extron	SW6 RGBHV A	909043021 E15251	Visible water damage in/around the component	
9	Extron	DA6 RGBHV	913964020 E15712	Visible water damage in/around the component	
10	Extron	DA6 RGBHV	913964002 E15712	Visible water damage in/around the component	
11	Extron	DA4 RGBHV	916805028 E15749	Visible water damage in/around the component	
12	Surgex	SX2120	785550	Visible water damage in/around the component	
13	Apple	A1392	N/A	Visible water damage in/around the component	
14	Tyco	10012 AC-2A	N/A	Visible water damage in/around the component	
15	Middle Atlantic	4715MS-12T-B10	N/A	Visible water damage in/around the component	
16	Symnet	BREAKIN12	800IN122B0018	Visible water damage in/around the component	
17	Symnet	8X8 DSP	800X686A0257	Visible water damage in/around the component	
18	Symnet	8X8 DSP	800X885A0241	Visible water damage in/around the component	
19	Symnet	8X8 DSP	8008X886A0256	Visible water damage in/around the component	
20	QSC	CX108V	110550151	Visible water damage in/around the component	
21	QSC	CX108V	110550155	Visible water damage in/around the component	
22	Shure	SCM820	201117234	Visible water damage in/around the component	
23	Middle Atlantic (Qty 2)	PD-1415C-NS	NA	Visible water damage in/around the component	
24	Middle Atlantic	MRK-4431	NA	Visible water damage in/around the component	
25	Middle Atlantic	MW-10 FT-FC	NA	Visible water damage in/around the component	
26	Creston	C2N-HBLOCK	6001923 1269655	Visible water damage in/around the component	
27	Symnet	8X8 DSP	8008X886A0264	Visible water damage in/around the component	
28	RDL	FP-MX4	NA	Visible water damage in/around the component	

PERFORMANCE

#	Brand	Model #	Status	Description	Recommendation
1	Extron	MSW 4V	Operational	Unit working during inspection	Replace
2	Extron	MSW 4V	Operational	Unit working during inspection	Replace
3	Extron	DA 6V EQ	Operational	Unit working during inspection	Replace
4	Creston	AV2	Operational	Unit working during inspection	Replace
5	Sennheiser	SI 1015	Operational	Unit working during inspection	Replace
6	Sennheiser	SI 1015	Operational	Unit working during inspection	Replace
7	Extron	SW6 RGBHV A	Operational	Unit working during inspection	Replace
8	Extron	SW6 RGBHV A	Operational	Unit working during inspection	Replace
9	Extron	DA6 RGBHV	Operational	Unit working during inspection	Replace
10	Extron	DA6 RGBHV	Operational	Unit working during inspection	Replace
11	Extron	DA4 RGBHV	Operational	Unit working during inspection	Replace
12	Surgex	SX2120	Operational	Unit working during inspection	Replace
13	Apple	A1392	Operational	Unit working during inspection	Replace
14	Tyco	10012 AC-2A	Operational	Unit working during inspection	Replace
15	Middle Atlantic	4715MS-12T-B10	Operational	Unit working during inspection	Replace
16	Symnet	BREAKIN12	Operational	Unit working during inspection	Replace
17	Symnet	8X8 DSP	Operational	Unit working during inspection	Replace
18	Symnet	8X8 DSP	Operational	Unit working during inspection	Replace
19	Symnet	8X8 DSP	Operational	Unit working during inspection	Replace
20	QSC	CX108V	Operational	Unit working during inspection	Replace
21	QSC	CX108V	Operational	Unit working during inspection	Replace
22	Shure	SCM820	Operational	Unit working during inspection	Replace
23	Middle Atlantic (Qty 2)	PD-1415C-NS	Operational	Unit working during inspection	Replace
24	Middle Atlantic	MRK-4431	Operational	Unit working during inspection	Replace
25	Middle Atlantic	MW-10 FT-FC	Operational	Unit working during inspection	Replace
26	Creston	C2N-HBLOCK	Operational	Unit working during inspection	Replace
27	Symnet	8X8 DSP	Not Compliant	Unit Failed / Not turning on	Replace
28	RDL	FP-MX4	Not Compliant	Unit Failed / Not turning on	Replace

CourtRoom 1B				EQUIPMENT LIST	
#	Brand	Model #	Serial #	Description	
1	Panasonic	PTRW330U	DE6210191	LED/ Laser 1-chip DLP, 3500 lumens, WXGA	
2	Speaker (Qty 8)	N/A	N/A	70V Commercial Ceiling Speaker	
3	Extron	CMP103	N/A	Three-Gang AV Connectivity Mounting Frame	
4	Extron	CMP103	N/A	Three-Gang AV Connectivity Mounting Frame	
5	Extron	CMP104	N/A	Three-Gang AV Connectivity Mounting Frame	
6	Shure (Qty 5)	MX4180/C	N/A	Microflex® Standard Gooseneck Microphone	
7	Crestron	TPS-12	N/A	12" Active Matrix Touchscreen Display	
8	Crestron	CNX RMC	6001328 1835702	Video Receiver and Control Interface	
9	Crestron	TPMC-CH-IMC	6002771 1780719	Balanced AV Interface Module for TPS-12	
10	Kramer	VP-419XL	1130165700047	Video to Computer Graphics Video/HDTV ProScale Digital Scaler	
11	Extron	SW4 RGBHVA	861278003	Four-Input RGBHV Switcher	
12	Sony	SLV-D370P	625522	Progressive-Scan DVD Player/VCR Combo	
13	Crestron	TPS-12	6002952 1903691	12" Active Matrix Touchscreen Display	
14	Extron	CPM 104	N/A	Three-Gang AV Connectivity Mounting Frame	
15	Crestron	TPMC-CH-IMC	6002771 1767009	Balanced AV Interface Module for TPS-12	
VISUAL INSPECTION					
#	Brand	Model #	Serial #	Description	
1	Panasonic	PTRW330U	DE6210191	Visible water damage in/around the component	
2	Speaker (Qty 8)	N/A	N/A	Visible water damage in/around the component	
3	Extron	CMP103	N/A	Visible water damage in/around the component	
4	Extron	CMP103	N/A	Visible water damage in/around the component	
5	Extron	CMP104	N/A	Visible water damage in/around the component	
6	Shure (Qty 5)	MX4180/C	N/A	Visible water damage in/around the component	
7	Crestron	TPS-12	N/A	Visible water damage in/around the component	
8	Crestron	CNX RMC	6001328 1835702	Visible water damage in/around the component	
9	Crestron	TPMC-CH-IMC	6002771 1780719	Visible water damage in/around the component	
10	Kramer	VP-419XL	1130165700047	Visible water damage in/around the component	
11	Extron	SW4 RGBHVA	861278003	Visible water damage in/around the component	
12	Sony	SLV-D370P	625522	Visible water damage in/around the component	
13	Crestron	TPS-12	6002952 1903691	Visible water damage in/around the component	
14	Extron	CPM 104	N/A	Visible water damage in/around the component	
15	Crestron	TPMC-CH-IMC	6002771 1767009	Visible water damage in/around the component	
PERFORMANCE					
#	Brand	Model #	Status	Description	Recommendation
1	Panasonic	PTRW330U	Operational	Unit working during inspection	Replace
2	Speaker (Qty 8)	N/A	Operational	Unit working during inspection	Replace
3	Extron	CMP103	Operational	Water Damage / Rusty	Replace
4	Extron	CMP103	Operational	Water Damage / Rusty	Replace
5	Extron	CMP104	Operational	Water Damage / Rusty	Replace
6	Shure (Qty 5)	MX4180/C	Operational	Unit working during inspection	Replace
7	Crestron	TPS-12	Not Compliant	Touch panel failed / Not turning on	Replace
8	Crestron	CNX RMC	Operational	Unit working during inspection	Replace
9	Crestron	TPMC-CH-IMC	Operational	Unit working during inspection	Replace
10	Kramer	VP-419XL	Operational	Unit working during inspection	Replace
11	Extron	SW4 RGBHVA	Operational	Unit working during inspection	Replace
12	Sony	SLV-D370P	Operational	Unit working during inspection	Replace
13	Crestron	TPS-12	Not Compliant	Touch panel failed / Not turning on	Replace
14	Extron	CPM 104	Operational	Unit working during inspection	Replace
15	Crestron	TPMC-CH-IMC	Operational	Unit working during inspection	Replace

Courtroom 2A				EQUIPMENT LIST	
#	Brand	Model #	Serial #	Description	
1	Extron	CMP-104	NA	Three-Gang AV Connectivity Mounting Frame	
2	Planar	SL5551	PJWVFCJA00147	55"-Class Full HD Commercial LED Display	
3	Shure (Qty 5)	MX4180/C	N/A	Microflex® Standard Gooseneck Microphone	
4	Extron	CMP-104	N/A	Three-Gang AV Connectivity Mounting Frame	
5	Extron	CMP-103	N/A	Three-Gang AV Connectivity Mounting Frame	
6	Apple	MC769LL/A	F5RKQY2KDFHW	Apple iPad 2 MC769LL/A Tablet	
7	Panasonic	PT-RW330U	DE6210190	LED/ Laser 1-chip DLP, 3500 lumens, WXGA	
8	Speakers (Qty 9)	N/A	N/A	70V Commercial Ceiling Speaker	
9	Sennheiser	SZI 1015-TW	N/A	Radiator With Integrated Modulator	
10	Extron	CMP-104	N/A	Three-Gang AV Connectivity Mounting Frame	
11	Extron	TLM100T	N/A	Secure Mounting Enclosure for iPad	
12	Crestron	TPMC-CH-IMC	6002771 1767067	Balanced AV Interface Module for TPS--12	
13	Crestron	TPMC-CH-IMC	N/A	Balanced AV Interface Module for TPS--12	
14	Crestron	CNX-RMC	6001328 6001328	Video Receiver and Control Interface	
15	Extron	SW4RGBHV A	861278006 E14853	Four-Input RGBHV Switcher	
16	Apple	MC769LL/A	F5RKQWTRDFHW	Apple iPad 2 MC769LL/A Tablet	
17	Extron	TLM100T	N/A	Secure Mounting Enclosure for iPad	
18	Sony	SLVD370P	625085	Progressive-Scan DVD Player/VCR Combo	
19	Sony	SLVD370P	598299	Progressive-Scan DVD Player/VCR Combo	
20	Deuce Mc	2220	QAA20050343	Video Encoder	
21	Deuce Mc	2220	QAA20050334	Video Encoder	

VISUAL INSPECTION

#	Brand	Model #	Serial #	Description	
1	Extron	CMP-104	NA	Visible water damage in/around the component	
2	Planar	SL5551	PJWVFCJA00147	Visible water damage in/around the component	
3	Shure (Qty 5)	MX4180/C	N/A	Visible water damage in/around the component	
4	Extron	CMP-104	N/A	Visible water damage in/around the component	
5	Extron	CMP-103	N/A	Visible water damage in/around the component	
6	Apple	MC769LL/A	F5RKQY2KDFHW	Visible water damage in/around the component	
7	Panasonic	PT-RW330U	DE6210190	Visible water damage in/around the component	
8	Speakers (Qty 9)	N/A	N/A	Visible water damage in/around the component	
9	Sennheiser	SZI 1015-TW	N/A	Visible water damage in/around the component	
10	Extron	CMP-104	N/A	Visible water damage in/around the component	
11	Extron	TLM100T	N/A	Visible water damage in/around the component	
12	Crestron	TPMC-CH-IMC	6002771 1767067	Visible water damage in/around the component	
13	Crestron	TPMC-CH-IMC	N/A	Visible water damage in/around the component	
14	Crestron	CNX-RMC	6001328 6001328	Visible water damage in/around the component	
15	Extron	SW4RGBHV A	861278006 E14853	Visible water damage in/around the component	
16	Apple	MC769LL/A	F5RKQWTRDFHW	Visible water damage in/around the component	
17	Extron	TLM100T	N/A	Visible water damage in/around the component	
18	Sony	SLVD370P	625085	Visible water damage in/around the component	
19	Sony	SLVD370P	598299	Visible water damage in/around the component	
20	Deuce Mc	2220	QAA20050343	Visible water damage in/around the component	
21	Deuce Mc	2220	QAA20050334	Visible water damage in/around the component	

PERFORMANCE

#	Brand	Model #	Status	Description	Recommendation
1	Extron	CMP-104	Operational	Water Damage / Rusty	Replace
2	Planar	SL5551	Operational	Unit working during inspection	Replace
3	Shure (Qty 5)	MX4180/C	Operational	Unit working during inspection	Replace
4	Extron	CMP-104	Operational	Water Damage / Rusty	Replace
5	Extron	CMP-103	Operational	Water Damage / Rusty	Replace
6	Apple	MC769LL/A	Operational	Unit working during inspection	Replace
7	Panasonic	PT-RW330U	Operational	Water Damage	Replace
8	Speakers (Qty 9)	N/A	Operational	Unit working during inspection	Replace
9	Sennheiser	SZI 1015-TW	Operational	Unit working during inspection	Replace
10	Extron	CMP-104	Operational	Unit working during inspection	Replace
11	Extron	TLM100T	Operational	Unit working during inspection	Replace
12	Crestron	TPMC-CH-IMC	Operational	Unit working during inspection	Replace
13	Crestron	TPMC-CH-IMC	Operational	Unit working during inspection	Replace
14	Crestron	CNX-RMC	Operational	Unit working during inspection	Replace
15	Extron	SW4RGBHV A	Operational	Unit working during inspection	Replace
16	Apple	MC769LL/A	Operational	Unit working during inspection	Replace
17	Extron	TLM100T	Operational	Unit working during inspection	Replace
18	Sony	SLVD370P	Operational	Unit working during inspection	Replace
19	Sony	SLVD370P	Operational	Unit working during inspection	Replace
20	Deuce Mc	2220	Operational	Unit working during inspection	Replace
21	Deuce Mc	2220	Operational	Unit working during inspection	Replace

Courtroom 2A & B Rack				EQUIPMENT LIST	
#	Brand	Model #	Serial #	Description	
1	Sennheiser	SI 1015	104725	Wideband Modulator	
2	Extron	SW4 RGBHV A	A0BGKAW E22843	Four-Input RGBHV Switcher	
3	Extron	DA6RGBHV	916788003 E15712	Six Output Wideband RGBHV Distribution Amplifier	
4	Middle Atlantic	MW-10FT-FC	N/A	10" Fan Mount with Fan Control	
5	Middle Atlantic	MRK-4431	N/A	MRK Series Rack, 44 RU, 31" D	
6	Middle Atlantic (Qty 2)	PD-615C-NS	N/A	6 Outlet, Single15 Amp Circuit Power Strip	
7	Middle Atlantic	SPN-44-312	N/A	Side Panels, 44 RU, 31-32"D Racks	
8	Crestron	AV2	6001376 1766584	Economical Dual Bus Control System	
9	Symnet	8X8 DSP	N/A	DSP Digital Signal Processor	
10	Symnet	8X8 DSP	N/A	DSP Digital Signal Processor	
11	Symnet	8X8 DSP	N/A	DSP Digital Signal Processor	
12	SurgeX	SX2120	785554	Rack mountable 20-amp Surge Suppressor/Power Conditioner with 15 Outlets	
13	Apple	A1392	C86QM108DV2R	AirPort Express 802.11n (2nd Generation)	
14	Tyco	10012 AC-2A	N/A	Paging System	
15	Sennheiser	SI 1015	104765	Wideband Modulator	
16	Extron	SW6 RGBHV A	919018012 E15727	Six-Input RGBHV Switcher	
17	Extron	DA6RGBHV	913962022 E15712	Six Output Wideband RGBHV Distribution Amplifier	
18	Middle Atlantic	4715MS-12T-B10	N/A	Rackmount Fan Assembly with Two Cooling Fans	
19	Qsc	CX302V	90553978	2-Channel 70V Power Amplifier	
20	Qsc	CX108V	110550174	8-Channel 70V Power Amplifier	
21	Crestron	C2N-HBLOCK	6001923 1659516	Multi-type Cresnet Distribution Block	

VISUAL INSPECTION

#	Brand	Model #	Serial #	Description	
1	Sennheiser	SI 1015	104725	Visible water damage in/around the component	
2	Extron	SW4 RGBHV A	A0BGKAW E22843	Visible water damage in/around the component	
3	Extron	DA6RGBHV	916788003 E15712	Visible water damage in/around the component	
4	Middle Atlantic	MW-10FT-FC	N/A	Visible water damage in/around the component	
5	Middle Atlantic	MRK-4431	N/A	Visible water damage in/around the component	
6	Middle Atlantic (Qty 2)	PD-615C-NS	N/A	Visible water damage in/around the component	
7	Middle Atlantic	SPN-44-312	N/A	Visible water damage in/around the component	
8	Crestron	AV2	6001376 1766584	Visible water damage in/around the component	
9	Symnet	8X8 DSP	N/A	Visible water damage in/around the component	
10	Symnet	8X8 DSP	N/A	Visible water damage in/around the component	
11	Symnet	8X8 DSP	N/A	Visible water damage in/around the component	
12	SurgeX	SX2120	785554	Visible water damage in/around the component	
13	Apple	A1392	C86QM108DV2R	Visible water damage in/around the component	
14	Tyco	10012 AC-2A	N/A	Visible water damage in/around the component	
15	Sennheiser	SI 1015	104765	Visible water damage in/around the component	
16	Extron	SW6 RGBHV A	919018012 E15727	Visible water damage in/around the component	
17	Extron	DA6RGBHV	913962022 E15712	Visible water damage in/around the component	
18	Middle Atlantic	4715MS-12T-B10	N/A	Visible water damage in/around the component	
19	QSC	CX302V	90553978	Visible water damage in/around the component	
20	QSC	CX108V	110550174	Visible water damage in/around the component	
21	Crestron	C2N-HBLOCK	6001923 1659516	Visible water damage in/around the component	

PERFORMANCE

#	Brand	Model #	Status	Description	Recommendation
1	Sennheiser	SI 1015	Operational	Unit working during inspection	Replace
2	Extron	SW4 RGBHV A	Operational	Unit working during inspection	Replace
3	Extron	DA6RGBHV	Operational	Unit working during inspection	Replace
4	Middle Atlantic	MW-10FT-FC	Operational	Unit working during inspection	Replace
5	Middle Atlantic	MRK-4431	Operational	Unit working during inspection	Replace
6	Middle Atlantic (Qty 2)	PD-615C-NS	Operational	Unit working during inspection	Replace
7	Middle Atlantic	SPN-44-312	Operational	Unit working during inspection	Replace
8	Crestron	AV2	Operational	Unit Failed / Not turning on	Replace
9	Symnet	8X8 DSP	Operational	Unit working during inspection	Replace
10	Symnet	8X8 DSP	Operational	Unit working during inspection	Replace
11	Symnet	8X8 DSP	Operational	Unit working during inspection	Replace
12	SurgeX	SX2120	Operational	Unit working during inspection	Replace
13	Apple	A1392	Operational	Unit working during inspection	Replace
14	Tyco	10012 AC-2A	Operational	Unit working during inspection	Replace
15	Sennheiser	SI 1015	Operational	Unit working during inspection	Replace
16	Extron	SW6 RGBHV A	Operational	Unit working during inspection	Replace
17	Extron	DA6RGBHV	Operational	Unit Failed / Not turning on	Replace
18	Middle Atlantic	4715MS-12T-B10	Operational	Unit working during inspection	Replace
19	QSC	CX302V	Operational	Unit working during inspection	Replace
20	QSC	CX108V	Operational	Unit working during inspection	Replace
21	Crestron	C2N-HBLOCK	Operational	Unit working during inspection	Replace

Courtroom 2B				EQUIPMENT LIST	
#	Brand	Model #	Serial #	Description	
1	Extron	CMP-104	N/A	Three-Gang AV Connectivity Mounting Frame	
2	Planar	SL5551	PJWVF9JA00171	55"-Class Full HD Commercial LED Display	
3	Shure (Qty 5)	MX4180/C	N/A	Microflex® Standard Gooseneck Microphone	
4	Extron	CMP-104	N/A	Three-Gang AV Connectivity Mounting Frame	
5	Extron	CMP-103	N/A	Three-Gang AV Connectivity Mounting Frame	
6	Apple	MC769LL/A	F5RKQUW3DFHW	Apple iPad 2 MC769LL/A Tablet	
7	Panasonic	PT-RW330U	DE6210184	LED/ Laser 1-chip DLP, 3500 lumens, WXGA	
8	Speakers (Qty 9)	N/A	N/A	70V Commercial Ceiling Speaker	
9	Sennheiser	SZI 1015-TW	N/A	Radiator With Integrated Modulator	
10	Extron	CMP-104	NA	Three-Gang AV Connectivity Mounting Frame	
11	Extron	TLM100T	N/A	Secure Mounting Enclosure for iPad	
12	Crestron	TPMC-CH-IMC	600271 1840010	Balanced AV Interface Module for TPS--12	
13	Crestron	TPMC-CH-IMC	600271 1780851	Balanced AV Interface Module for TPS--12	
14	Crestron	CNX-RMC	6001328 1835711	Video Receiver and Control Interface	
15	Extron	SW4RGBHV A	861278004 E14853	Four-Input RGBHV Switcher	
16	Apple	MC769LL/A	N/A	Apple iPad 2 MC769LL/A Tablet	
17	Extron	TLM100T	N/A	Secure Mounting Enclosure for iPad	

VISUAL INSPECTION

#	Brand	Model #	Serial #	Description	
1	Extron	CMP-104	N/A	Visible water damage in/around the component	
2	Planar	SL5551	PJWVF9JA00171	Visible water damage in/around the component	
3	Shure (Qty 5)	MX4180/C	N/A	Visible water damage in/around the component	
4	Extron	CMP-104	N/A	Visible water damage in/around the component	
5	Extron	CMP-103	N/A	Visible water damage in/around the component	
6	Apple	MC769LL/A	F5RKQUW3DFHW	Visible water damage in/around the component	
7	Panasonic	PT-RW330U	DE6210184	Visible water damage in/around the component	
8	Speakers (Qty 9)	N/A	N/A	Visible water damage in/around the component	
9	Sennheiser	SZI 1015-TW	N/A	Visible water damage in/around the component	
10	Extron	CMP-104	N/A	Visible water damage in/around the component	
11	Extron	TLM100T	N/A	Visible water damage in/around the component	
12	Crestron	TPMC-CH-IMC	600271 1840010	Visible water damage in/around the component	
13	Crestron	TPMC-CH-IMC	600271 1780851	Visible water damage in/around the component	
14	Crestron	CNX-RMC	6001328 1835711	Visible water damage in/around the component	
15	Extron	SW4RGBHV A	861278004 E14853	Visible water damage in/around the component	
16	Apple	MC769LL/A	N/A	Visible water damage in/around the component	
17	Extron	TLM100T	N/A	Visible water damage in/around the component	

PERFORMANCE

#	Brand	Model #	Status	Description	Recommendation
1	Extron	CMP-104	Operational	Water Damage / Rusty	Replace
2	Planar	SL5551	Operational	Unit working during inspection	Replace
3	Shure (Qty 5)	MX4180/C	Operational	Unit working during inspection	Replace
4	Extron	CMP-104	Operational	Water Damage / Rusty	Replace
5	Extron	CMP-103	Operational	Water Damage / Rusty	Replace
6	Apple	MC769LL/A	Operational	Unit working during inspection	Replace
7	Panasonic	PT-RW330U	Operational	Water Damage	Replace
8	Speakers (Qty 9)	N/A	Operational	Unit working during inspection	Replace
9	Sennheiser	SZI 1015-TW	Operational	Unit working during inspection	Replace
10	Extron	CMP-104	Operational	Unit working during inspection	Replace
11	Extron	TLM100T	Operational	Unit working during inspection	Replace
12	Crestron	TPMC-CH-IMC	Operational	Unit working during inspection	Replace
13	Crestron	TPMC-CH-IMC	Operational	Unit working during inspection	Replace
14	Crestron	CNX-RMC	Operational	Unit working during inspection	Replace
15	Extron	SW4RGBHV A	Operational	Unit working during inspection	Replace
16	Apple	MC769LL/A	Not Compliant	Water Damage	Replace
17	Extron	TLM100T	Operational	Unit working during inspection	Replace

Courtroom 2C		EQUIPMENT LIST			
#	Brand	Model #	Serial #	Description	
1	Extron	CMP-104	N/A	Three-Gang AV Connectivity Mounting Frame	
2	Shure (Qty 5)	MX4180/C	N/A	Microflex® Standard Gooseneck Microphone	
3	Extron	CMP-104	N/A	Three-Gang AV Connectivity Mounting Frame	
4	Extron	CMP-103	N/A	Three-Gang AV Connectivity Mounting Frame	
5	Apple	MC954LL/A	DYTKR075DFHW	Apple iPad 2 MC769LL/A Tablet	
6	Panasonic	PT-RW330U	DE6210116	LED/ Laser 1-chip DLP, 3500 lumens, WXGA	
7	Speakers (Qty 9)	N/A	N/A	70V Commercial Ceiling Speaker	
8	Sennheiser	SZI 1015-TW	N/A	Radiator With Integrated Modulator	
9	Extron	CMP-104	N/A	Three-Gang AV Connectivity Mounting Frame	
10	Extron	TLM100T	N/A	Secure Mounting Enclosure for iPad	
11	Crestron	TPMC-CH-IMC	6002771 1767167	Balanced AV Interface Module for TPS--12	
12	Crestron	TPMC-CH-IMC	600271 1421928	Balanced AV Interface Module for TPS--12	
13	Crestron	CNX-RMC	6001328 11835736	Video Receiver and Control Interface	
14	Extron	SW4RGBHV A	861278008 E14853	Four-Input RGBHV Switcher	
15	Apple	MC769LL/A	N/A	Apple iPad 2 MC769LL/A Tablet	
16	Extron	TLM100T	N/A	Secure Mounting Enclosure for iPad	
VISUAL INSPECTION					
#	Brand	Model #	Serial #	Description	
1	Extron	CMP-104	N/A	Visible water damage in/around the component	
2	Shure (Qty 5)	MX4180/C	N/A	Visible water damage in/around the component	
3	Extron	CMP-104	N/A	Visible water damage in/around the component	
4	Extron	CMP-103	N/A	Visible water damage in/around the component	
5	Apple	MC954LL/A	DYTKR075DFHW	Visible water damage in/around the component	
6	Panasonic	PT-RW330U	DE6210116	Visible water damage in/around the component	
7	Speakers (Qty 9)	N/A	N/A	Visible water damage in/around the component	
8	Sennheiser	SZI 1015-TW	N/A	Visible water damage in/around the component	
9	Extron	CMP-104	N/A	Visible water damage in/around the component	
10	Extron	TLM100T	N/A	Visible water damage in/around the component	
11	Crestron	TPMC-CH-IMC	6002771 1767167	Visible water damage in/around the component	
12	Crestron	TPMC-CH-IMC	600271 1421928	Visible water damage in/around the component	
13	Crestron	CNX-RMC	6001328 11835736	Visible water damage in/around the component	
14	Extron	SW4RGBHV A	861278008 E14853	Visible water damage in/around the component	
15	Apple	MC769LL/A	N/A	Visible water damage in/around the component	
16	Extron	TLM100T	N/A	Visible water damage in/around the component	
PERFORMANCE					
#	Brand	Model #	Status	Description	Recommendation
1	Extron	CMP-104	Operational	Unit working during inspection	Replace
2	Shure (Qty 5)	MX4180/C	Operational	Unit working during inspection	Replace
3	Extron	CMP-104	Operational	Water Damage / Rusty	Replace
4	Extron	CMP-103	Operational	Water Damage / Rusty	Replace
5	Apple	MC954LL/A	Operational	Unit working during inspection	Replace
6	Panasonic	PT-RW330U	Operational	Unit working during inspection	Replace
7	Speakers (Qty 9)	N/A	Operational	Water Damage	Replace
8	Sennheiser	SZI 1015-TW	Operational	Unit working during inspection	Replace
9	Extron	CMP-104	Operational	Unit working during inspection	Replace
10	Extron	TLM100T	Operational	Unit working during inspection	Replace
11	Crestron	TPMC-CH-IMC	Operational	Unit working during inspection	Replace
12	Crestron	TPMC-CH-IMC	Operational	Unit working during inspection	Replace
13	Crestron	CNX-RMC	Operational	Unit working during inspection	Replace
14	Extron	SW4RGBHV A	Operational	Unit working during inspection	Replace
15	Apple	MC769LL/A	Operational	Unit working during inspection	Replace
16	Extron	TLM100T	Operational	Unit working during inspection	Replace

Courtroom 2 C & D Rack				
EQUIPMENT LIST				
#	Brand	Model #	Serial #	Description
1	Sennheiser	SI 1015	115777	Wideband Modulator
2	Extron	SW6 RGBHV A	A0HKC6P E24043	Six-Input RGBHV Switcher
3	Extron	DA6RGBHV	913964025 E15712	Six Output Wideband RGBHV Distribution Amplifier
4	Middle Atlantic	MW-10FT-FC	N/A	10" Fan Mount with Fan Control
5	Middle Atlantic	MRK-4431	N/A	MRK Series Rack, 44 RU, 31" D
6	Middle Atlantic (Qty 2)	PD-615C-NS	N/A	6 Outlet, Single 5 Amp Circuit Power Strip
7	Middle Atlantic	SPN-44-312	N/A	SPN Universal Side Panels
8	Crestron	PRO2	6001377 1330161	Professional Dual Bus Control System
9	Shure	SCM820	201117214	Digital IntelliMix Automatic Mixer
10	Symnet	8X8 DSP	8008X886A0263	DSP Digital Signal Processor
11	Shure	SCM820	201117223	Digital IntelliMix Automatic Mixer
12	SurgeX	SX2120	785552	Rackmountable 20-amp Surge Suppressor/Power Conditioner with 15 Outlets
13	Apple	A1392	C86QM108DV2R	AirPort Express 802.11n (2nd Generation)
14	Tyco	10012 AC-2A	N/A	Paging System
15	Sennheiser	SI 1015	105488	Wideband Modulator
16	Extron	SW6 RGBHV A	909043020 E15251	Six-Input RGBHV Switcher
17	Extron	DA6RGBHV	916788025 E15712	Six Output Wideband RGBHV Distribution Amplifier
18	Middle Atlantic	4715MS-12T-B10	N/A	Rackmount Fan Assembly with Two Cooling Fans
19	QSC	CX302V	90553906	2-Channel 70V Power Amplifier
20	QSC	CX108V	40653933	8-Channel 70V Power Amplifier
21	Crestron	C2N-HBLOCK	6001923 1659518	Multi-type Cresnet Distribution Block

VISUAL INSPECTION

#	Brand	Model #	Serial #	Description
1	Sennheiser	SI 1015	115777	Visible water damage in/around the component
2	Extron	SW6 RGBHV A	A0HKC6P E24043	Visible water damage in/around the component
3	Extron	DA6RGBHV	913964025 E15712	Visible water damage in/around the component
4	Middle Atlantic	MW-10FT-FC	N/A	Visible water damage in/around the component
5	Middle Atlantic	MRK-4431	N/A	Visible water damage in/around the component
6	Middle Atlantic (Qty 2)	PD-615C-NS	N/A	Visible water damage in/around the component
7	Middle Atlantic	SPN-44-312	N/A	Visible water damage in/around the component
8	Crestron	PRO2	6001377 1330161	Visible water damage in/around the component
9	Shure	SCM820	201117214	Visible water damage in/around the component
10	Symnet	8X8 DSP	8008X886A0263	Visible water damage in/around the component
11	Shure	SCM820	201117223	Visible water damage in/around the component
12	SurgeX	SX2120	785552	Visible water damage in/around the component
13	Apple	A1392	C86QM108DV2R	Visible water damage in/around the component
14	Tyco	10012 AC-2A	N/A	Visible water damage in/around the component
15	Sennheiser	SI 1015	105488	Visible water damage in/around the component
16	Extron	SW6 RGBHV A	909043020 E15251	Visible water damage in/around the component
17	Extron	DA6RGBHV	916788025 E15712	Visible water damage in/around the component
18	Middle Atlantic	4715MS-12T-B10	N/A	Visible water damage in/around the component
19	QSC	CX302V	90553906	Visible water damage in/around the component
20	QSC	CX108V	40653933	Visible water damage in/around the component
21	Crestron	C2N-HBLOCK	6001923 1659518	Visible water damage in/around the component

PERFORMANCE

#	Brand	Model #	Status	Description	Recommendation
1	Sennheiser	SI 1015	Operational	Unit working during inspection	Replace
2	Extron	SW6 RGBHV A	Operational	Unit working during inspection	Replace
3	Extron	DA6RGBHV	Operational	Unit working during inspection	Replace
4	Middle Atlantic	MW-10FT-FC	Operational	Unit working during inspection	Replace
5	Middle Atlantic	MRK-4431	Operational	Unit working during inspection	Replace
6	Middle Atlantic (Qty 2)	PD-615C-NS	Operational	Unit working during inspection	Replace
7	Middle Atlantic	SPN-44-312	Operational	Unit working during inspection	Replace
8	Crestron	PRO2	Operational	Unit working during inspection	Replace
9	Shure	SCM820	Operational	Unit working during inspection	Replace
10	Symnet	8X8 DSP	Operational	Unit working during inspection	Replace
11	Shure	SCM820	Operational	Unit working during inspection	Replace
12	SurgeX	SX2120	Operational	Unit working during inspection	Replace
13	Apple	A1392	Operational	Unit working during inspection	Replace
14	Tyco	10012 AC-2A	Operational	Unit working during inspection	Replace
15	Sennheiser	SI 1015	Operational	Unit working during inspection	Replace
16	Extron	SW6 RGBHV A	Operational	Unit working during inspection	Replace
17	Extron	DA6RGBHV	Operational	Unit working during inspection	Replace
18	Middle Atlantic	4715MS-12T-B10	Operational	Unit working during inspection	Replace
19	QSC	CX302V	Operational	Unit working during inspection	Replace
20	QSC	CX108V	Operational	Unit working during inspection	Replace
21	Crestron	C2N-HBLOCK	Operational	Unit working during inspection	Replace

Courtroom 2D		EQUIPMENT LIST			
#	Brand	Model #	Serial #	Description	
1	Extron	CMP-104	N/A	Three-Gang AV Connectivity Mounting Frame	
2	Shure (Qty 5)	MX4180/C	N/A	Microflex® Standard Gooseneck Microphone	
3	Extron	CMP-104	N/A	Three-Gang AV Connectivity Mounting Frame	
4	Extron	CMP-103	N/A	Three-Gang AV Connectivity Mounting Frame	
5	Apple	MC954LL/A	FSRKQZE5E5DFHW	Apple iPad 2 MC769LL/A Tablet	
6	Panasonic	PT-RW330U	DE6210145	LED/ Laser 1-chip DLP, 3500 lumens, WXGA	
7	Speakers (Qty 9)	N/A	N/A	70V Commercial Ceiling Speaker	
8	Sennheiser	SZI 1015-TW	N/A	Radiator With Integrated Modulator	
9	Extron	CMP-104	N/A	Three-Gang AV Connectivity Mounting Frame	
10	Extron	TLM100T	N/A	Secure Mounting Enclosure for iPad	
11	Crestron	TPMC-CH-IMC	6002771 17800728	Balanced AV Interface Module for TPS--12	
12	Crestron	TPMC-CH-IMC	600271 1839999	Balanced AV Interface Module for TPS--12	
13	Crestron	CNX-RMC	6001328 1835693	Video Receiver and Control Interface	
14	Extron	SW4RGBHV A	86278022 E14853	Four-Input RGBHV Switcher	
15	Crestron	TPS-12	6002952 1905670	12" Active Matrix Touchscreen Display	
VISUAL INSPECTION					
#	Brand	Model #	Serial #	Description	
1	Extron	CMP-104	N/A	No visible noticable damage to report	
2	Shure (Qty 5)	MX4180/C	N/A	No visible noticable damage to report	
3	Extron	CMP-104	N/A	No visible noticable damage to report	
4	Extron	CMP-103	N/A	No visible noticable damage to report	
5	Apple	MC954LL/A	FSRKQZE5E5DFHW	No visible noticable damage to report	
6	Panasonic	PT-RW330U	DE6210145	No visible noticable damage to report	
7	Speakers (Qty 9)	N/A	N/A	No visible noticable damage to report	
8	Sennheiser	SZI 1015-TW	N/A	No visible noticable damage to report	
9	Extron	CMP-104	N/A	No visible noticable damage to report	
10	Extron	TLM100T	N/A	No visible noticable damage to report	
11	Crestron	TPMC-CH-IMC	6002771 17800728	No visible noticable damage to report	
12	Crestron	TPMC-CH-IMC	600271 1839999	No visible noticable damage to report	
13	Crestron	CNX-RMC	6001328 1835693	No visible noticable damage to report	
14	Extron	SW4RGBHV A	86278022 E14853	No visible noticable damage to report	
15	Crestron	TPS-12	6002952 1905670	No visible noticable damage to report	
PERFORMANCE					
#	Brand	Model #	Status	Description	Recommendation
1	Extron	CMP-104	Operational	No apparence issues	Good
2	Shure (Qty 5)	MX4180/C	Operational	No apparence issues	Good
3	Extron	CMP-104	Operational	No apparence issues	Good
4	Extron	CMP-103	Operational	No apparence issues	Good
5	Apple	MC954LL/A	Operational	No apparence issues	Good
6	Panasonic	PT-RW330U	Operational	No apparence issues	Good
7	Speakers (Qty 9)	N/A	Operational	No apparence issues	Good
8	Sennheiser	SZI 1015-TW	Operational	No apparence issues	Good
9	Extron	CMP-104	Operational	No apparence issues	Good
10	Extron	TLM100T	Operational	No apparence issues	Good
11	Crestron	TPMC-CH-IMC	Operational	No apparence issues	Good
12	Crestron	TPMC-CH-IMC	Operational	No apparence issues	Good
13	Crestron	CNX-RMC	Operational	No apparence issues	Good
14	Extron	SW4RGBHV A	Operational	No apparence issues	Good
15	Crestron	TPS-12	Operational	No apparence issues	Good

Courtroom 3A		EQUIPMENT LIST			
#	Brand	Model #	Serial #	Description	
1	Extron	CMP-104	N/A	Three-Gang AV Connectivity Mounting Frame	
2	Crestron	TPS-12	6002952 1876026	12" Active Matrix Touchscreen Display	
3	Shure (Qty 5)	MX4180/C	N/A	Microflex® Standard Gooseneck Microphone	
4	Extron	CMP-104	N/A	Three-Gang AV Connectivity Mounting Frame	
5	Extron	CMP-103	N/A	Three-Gang AV Connectivity Mounting Frame	
6	Crestron	TPMC-CH-IMC	6002771 1840006	Balanced AV Interface Module for TPS--12	
7	Panasonic	PT-RW330U	DE6210189	LED/ Laser 1-chip DLP, 3500 lumens, WXGA	
8	Speakers (Qty 9)	N/A	N/A	70V Commercial Ceiling Speaker	
9	Sennheiser	SZI 1015-TW	N/A	Radiator With Integrated Modulator	
10	Extron	CMP-104	N/A	Three-Gang AV Connectivity Mounting Frame	
11	Crestron	TPMC-CH-IMC	600271 1766987	Balanced AV Interface Module for TPS--12	
12	Crestron	CNX-RMC	6001328 1835688	Video Receiver and Control Interface	
13	Extron	SW4RGBHV A	861278020 E14853	Four-Input RGBHV Switcher	
14	Sony	SLV-D370P	625524	Progressive-Scan DVD Player/VCR Combo	
15	Deuce	2220	QAA20050348	Video Encoder	
VISUAL INSPECTION					
#	Brand	Model #	Serial #	Description	
1	Extron	CMP-104	N/A	Visible water damage in/around the component	
2	Crestron	TPS-12	6002952 1876026	Visible water damage in/around the component	
3	Shure (Qty 5)	MX4180/C	N/A	Visible water damage in/around the component	
4	Extron	CMP-104	N/A	Visible water damage in/around the component	
5	Extron	CMP-103	N/A	Visible water damage in/around the component	
6	Crestron	TPMC-CH-IMC	6002771 1840006	Visible water damage in/around the component	
7	Panasonic	PT-RW330U	DE6210189	Visible water damage in/around the component	
8	Speakers (Qty 9)	N/A	N/A	Visible water damage in/around the component	
9	Sennheiser	SZI 1015-TW	N/A	Visible water damage in/around the component	
10	Extron	CMP-104	N/A	Visible water damage in/around the component	
11	Crestron	TPMC-CH-IMC	600271 1766987	Visible water damage in/around the component	
12	Crestron	CNX-RMC	6001328 1835688	Visible water damage in/around the component	
13	Extron	SW4RGBHV A	861278020 E14853	Visible water damage in/around the component	
14	Sony	SLV-D370P	625524	Visible water damage in/around the component	
15	Deuce	2220	QAA20050348	Visible water damage in/around the component	
PERFORMANCE					
#	Brand	Model #	Status	Description	Recommendation
1	Extron	CMP-104	Operational	Water Damage / Rusty	Replace
2	Crestron	TPS-12	Not Compliant	Touch panel failed / Not turning on	Replace
3	Shure (Qty 5)	MX4180/C	Operational	Water Damage / Rusty	Replace
4	Extron	CMP-104	Operational	Water Damage / Rusty	Replace
5	Extron	CMP-103	Operational	Water Damage / Rusty	Replace
6	Crestron	TPMC-CH-IMC	Operational	Unit working during inspection	Replace
7	Panasonic	PT-RW330U	Operational	Water Damage	Replace
8	Speakers (Qty 9)	N/A	Operational	Unit working during inspection	Replace
9	Sennheiser	SZI 1015-TW	Operational	Unit working during inspection	Replace
10	Extron	CMP-104	Operational	Unit working during inspection	Replace
11	Crestron	TPMC-CH-IMC	Operational	Unit working during inspection	Replace
12	Crestron	CNX-RMC	Operational	Unit working during inspection	Replace
13	Extron	SW4RGBHV A	Operational	Unit working during inspection	Replace
14	Sony	SLV-D370P	Operational	Unit working during inspection	Replace
15	Deuce	2220	Operational	Unit working during inspection	Replace

Courtroom 3B

EQUIPMENT LIST

#	Brand	Model #	Serial #	Description
1	Extron	CMP-104	N/A	Three-Gang AV Connectivity Mounting Frame
2	Apple	MC769LL/A	FSRKQZJ8DFHW	Apple iPad 2 MC769LL/A Tablet
3	Shure (Qty 6)	MX4180/C	N/A	Microflex® Standard Gooseneck Microphone
4	Extron	CMP-103	NA	Three-Gang AV Connectivity Mounting Frame
5	Extron	CMP-103	NA	Three-Gang AV Connectivity Mounting Frame
6	Crestron	TPMC-CH-IMC	6002771 1767096	Balanced AV Interface Module for TPS-12
7	Panasonic	PT-RW330U	DE6210131	LED/ Laser 1-chip DLP, 3500 lumens, WXGA
8	Speaker (Qty 9)	N/A	N/A	70V Commercial Ceiling Speaker
9	Sennheiser	SZI 1015-TW	N/A	Radiator With Integrated Modulator
10	Extron	CMP-104	NA	Three-Gang AV Connectivity Mounting Frame
11	Extron	TLM-100T	N/A	Secure Mounting Enclosure for iPad
12	Crestron	TPMC-CH-IMC	N/A	Balanced AV Interface Module for TPS-12
13	Crestron	CNX-RMC	6001328 2066713	Video Receiver and Control Interface
14	Extron	SW4RGBHV A	861278024 E14853	Four-Input RGBHV Switch
15	Sony	SLV-D370P	N/A	Progressive-Scan DVD Player/VCR Combo
16	Deuce	2220	QAA20050342	Video Encoder

VISUAL INSPECTION

#	Brand	Model #	Serial #	Description
1	Extron	CMP-104	N/A	Visible water damage in/around the component
2	Apple	MC769LL/A	FSRKQZJ8DFHW	Visible water damage in/around the component
3	Shure (Qty 6)	MX4180/C	N/A	Visible water damage in/around the component
4	Extron	CMP-103	NA	Visible water damage in/around the component
5	Extron	CMP-103	NA	Visible water damage in/around the component
6	Crestron	TPMC-CH-IMC	6002771 1767096	Visible water damage in/around the component
7	Panasonic	PT-RW330U	DE6210131	Visible water damage in/around the component
8	Speaker (Qty 9)	N/A	N/A	Visible water damage in/around the component
9	Sennheiser	SZI 1015-TW	N/A	Visible water damage in/around the component
10	Extron	CMP-104	NA	Visible water damage in/around the component
11	Extron	TLM-100T	N/A	Visible water damage in/around the component
12	Crestron	TPMC-CH-IMC	N/A	Visible water damage in/around the component
13	Crestron	CNX-RMC	6001328 2066713	Visible water damage in/around the component
14	Extron	SW4RGBHV A	861278024 E14853	Visible water damage in/around the component
15	Sony	SLV-D370P	N/A	Visible water damage in/around the component
16	Deuce	2220	QAA20050342	Visible water damage in/around the component

PERFORMANCE

#	Brand	Model #	Status	Description	Recommendation
1	Extron	CMP-104	Operational	Water Damage / Rusty	Replace
2	Apple	MC769LL/A	Operational	Unit working during inspection	Replace
3	Shure (Qty 6)	MX4180/C	Operational	Unit working during inspection	Replace
4	Extron	CMP-103	Operational	Water Damage / Rusty	Replace
5	Extron	CMP-103	Operational	Water Damage / Rusty	Replace
6	Crestron	TPMC-CH-IMC	Operational	Unit working during inspection	Replace
7	Panasonic	PT-RW330U	Operational	Water Damage	Replace
8	Speaker (Qty 9)	N/A	Operational	Unit working during inspection	Replace
9	Sennheiser	SZI 1015-TW	Operational	Unit working during inspection	Replace
10	Extron	CMP-104	Operational	Unit working during inspection	Replace
11	Extron	TLM-100T	Operational	Unit working during inspection	Replace
12	Crestron	TPMC-CH-IMC	Operational	Unit working during inspection	Replace
13	Crestron	CNX-RMC	Operational	Unit working during inspection	Replace
14	Extron	SW4RGBHV A	Operational	Unit working during inspection	Replace
15	Sony	SLV-D370P	Operational	Unit working during inspection	Replace
16	Deuce	2220	Operational	Unit working during inspection	Replace

Courtroom 3A & B Rack EQUIPMENT LIST

#	Brand	Model #	Serial #	Description
1	Sennheiser	SI 1015	104725	Wideband Modulator
2	Extron	SW4 RGBHV A	A0BGKAW E22843	Four-Input RGBHV Switcher
3	Extron	DA6RGBHV	916788003 E15712	Six Output Wideband RGBHV Distribution Amplifier
4	Middle Atlantic	MW-10FT-FC	N/A	10" Fan Mount with Fan Control
5	Middle Atlantic	MRK-4431	N/A	MRK Series Rack, 44 RU, 31" D
6	Middle Atlantic (Qty 2)	PD-615C-NS	N/A	6 Outlet, Single15 Amp Circuit Power Strip
7	Middle Atlantic	SPN-44-312	N/A	Side Panels, 44 RU, 31-32"D Racks
8	Crestron	AV2	6001376 1766584	Economical Dual Bus Control System
9	Symnet	8X8 DSP	N/A	DSP Digital Signal Processor
10	Symnet	8X8 DSP	N/A	DSP Digital Signal Processor
11	Symnet	8X8 DSP	N/A	DSP Digital Signal Processor
12	SurgeX	SX2120	785554	Rackmountable 20-amp Surge Suppressor/Power Conditioner with 15 Outlets
13	Apple	A1392	C86QM108DV2R	AirPort Express 802.11n (2nd Generation)
14	Tyco	10012 AC-2A	N/A	Paging System
15	Sennheiser	SI 1015	104765	Wideband Modulator
16	Extron	SW6 RGBHV A	919018012 E15727	Six-Input RGBHV Switcher
17	Extron	DA6RGBHV	913962022 E15712	Six Output Wideband RGBHV Distribution Amplifier
18	Middle Atlantic	4715MS-12T-B10	N/A	Rackmount Fan Assembly with Two Cooling Fans
19	QSC	CX302V	90553978	2-Channel 70V Power Amplifier
20	QSC	CX108V	110550174	8-Channel 70V Power Amplifier
21	Crestron	C2N-HBLOCK	6001923 1659516	Multi-type Cresnet Distribution Block

VISUAL INSPECTION

#	Brand	Model #	Serial #	Description
1	Sennheiser	SI 1015	104725	Visible water damage in/around the component
2	Extron	SW4 RGBHV A	A0BGKAW E22843	Visible water damage in/around the component
3	Extron	DA6RGBHV	916788003 E15712	Visible water damage in/around the component
4	Middle Atlantic	MW-10FT-FC	N/A	Visible water damage in/around the component
5	Middle Atlantic	MRK-4431	N/A	Visible water damage in/around the component
6	Middle Atlantic (Qty 2)	PD-615C-NS	N/A	Visible water damage in/around the component
7	Middle Atlantic	SPN-44-312	N/A	Visible water damage in/around the component
8	Crestron	AV2	6001376 1766584	Visible water damage in/around the component
9	Symnet	8X8 DSP	N/A	Visible water damage in/around the component
10	Symnet	8X8 DSP	N/A	Visible water damage in/around the component
11	Symnet	8X8 DSP	N/A	Visible water damage in/around the component
12	SurgeX	SX2120	785554	Visible water damage in/around the component
13	Apple	A1392	C86QM108DV2R	Visible water damage in/around the component
14	Tyco	10012 AC-2A	N/A	Visible water damage in/around the component
15	Sennheiser	SI 1015	104765	Visible water damage in/around the component
16	Extron	SW6 RGBHV A	919018012 E15727	Visible water damage in/around the component
17	Extron	DA6RGBHV	913962022 E15712	Visible water damage in/around the component
18	Middle Atlantic	4715MS-12T-B10	N/A	Visible water damage in/around the component
19	QSC	CX302V	90553978	Visible water damage in/around the component
20	QSC	CX108V	110550174	Visible water damage in/around the component
21	Crestron	C2N-HBLOCK	6001923 1659516	Visible water damage in/around the component

PERFORMANCE

#	Brand	Model #	Status	Description	Recommendation
1	Sennheiser	SI 1015	Operational	Unit working during inspection	Replace
2	Extron	SW4 RGBHV A	Operational	Unit working during inspection	Replace
3	Extron	DA6RGBHV	Operational	Unit working during inspection	Replace
4	Middle Atlantic	MW-10FT-FC	Operational	Unit working during inspection	Replace
5	Middle Atlantic	MRK-4431	Operational	Unit working during inspection	Replace
6	Middle Atlantic (Qty 2)	PD-615C-NS	Operational	Unit working during inspection	Replace
7	Middle Atlantic	SPN-44-312	Operational	Unit working during inspection	Replace
8	Crestron	AV2	Operational	Unit working during inspection	Replace
9	Symnet	8X8 DSP	Operational	Unit working during inspection	Replace
10	Symnet	8X8 DSP	Operational	Unit working during inspection	Replace
11	Symnet	8X8 DSP	Operational	Unit working during inspection	Replace
12	SurgeX	SX2120	Operational	Unit working during inspection	Replace
13	Apple	A1392	Operational	Unit working during inspection	Replace
14	Tyco	10012 AC-2A	Operational	Unit working during inspection	Replace
15	Sennheiser	SI 1015	Operational	Unit working during inspection	Replace
16	Extron	SW6 RGBHV A	Operational	Unit working during inspection	Replace
17	Extron	DA6RGBHV	Operational	Unit working during inspection	Replace
18	Middle Atlantic	4715MS-12T-B10	Operational	Unit working during inspection	Replace
19	QSC	CX302V	Operational	Unit working during inspection	Replace
20	QSC	CX108V	Operational	Unit working during inspection	Replace
21	Crestron	C2N-HBLOCK	Operational	Unit working during inspection	Replace

Courtroom 3C		EQUIPMENT LIST			
#	Brand	Model #	Serial #	Description	
1	Extron	CMP-104	N/A	Three-Gang AV Connectivity Mounting Frame	
2	Apple	MX4180/C	N/A	Microflex® Standard Gooseneck Microphone	
3	Shure (Qty 5)	CMP-104	N/A	Three-Gang AV Connectivity Mounting Frame	
4	Extron	CMP-103	N/A	Three-Gang AV Connectivity Mounting Frame	
5	Extron	MC954LL/A	N/A	Apple iPad 2 MC769LL/A Tablet	
6	Crestron	PT-RW330U	6002771 1840011	LED/ Laser 1-chip DLP, 3500 lumens, WXGA	
7	Panasonic	N/A	DE6210171	70V Commercial Ceiling Speaker	
8	Extron	SZI 1015-TW	N/A	Radiator With Integrated Modulator	
9	Sennheiser	CMP-104	N/A	Three-Gang AV Connectivity Mounting Frame	
10	Speakers (Qty 9)	TLM100T	N/A	Secure Mounting Enclosure for iPad	
11	Extron	TPMC-CH-IMC	N/A	Balanced AV Interface Module for TPS--12	
12	Crestron	TPMC-CH-IMC	6002771 1767125	Balanced AV Interface Module for TPS--12	
13	Crestron	CNX-RMC	6001328 1835871	Video Receiver and Control Interface	
14	Extron	SW4RGBHV A	861278024 E15727	Four-Input RGBHV Switcher	
15	iPad	MC769LL/A	N/A	Apple iPad 2 MC769LL/A Tablet	
VISUAL INSPECTION					
#	Brand	Model #	Serial #	Description	
1	Extron	CMP-104	N/A	Visible water damage in/around the component	
2	Apple	MC769LL/A	N/A	Visible water damage in/around the component	
3	Shure (Qty 5)	MX4180/C	N/A	Visible water damage in/around the component	
4	Extron	CMP-104	N/A	Visible water damage in/around the component	
5	Extron	CMP-103	N/A	Visible water damage in/around the component	
6	Crestron	TPMC-CH-IMC	6002771 1840011	Visible water damage in/around the component	
7	Panasonic	PT-RW330U	DE6210171	Visible water damage in/around the component	
8	Extron	CMP-104	N/A	Visible water damage in/around the component	
9	Sennheiser	SZI 1015-TW	N/A	Visible water damage in/around the component	
10	Speakers (Qty 9)	N/A	N/A	Visible water damage in/around the component	
11	Extron	TLM 100T	N/A	Visible water damage in/around the component	
12	Crestron	TPMC-CH-IMC	6002771 1767125	Visible water damage in/around the component	
13	Crestron	CNX-RMC	6001328 1835871	Visible water damage in/around the component	
14	Extron	SW4RGBHV A	861278024 E15727	Visible water damage in/around the component	
15	iPad	MC769LL/A	N/A	Visible water damage in/around the component	
PERFORMANCE					
#	Brand	Model #	Status	Description	Recommendation
1	Extron	CMP-104	Operational	Water Damage / Rusty	Replace
2	Apple	MC769LL/A	Operational	Unit working during inspection	Replace
3	Shure (Qty 5)	MX4180/C	Operational	Water Damage /Unit working during inspection	Replace
4	Extron	CMP-104	Operational	Water Damage / Rusty	Replace
5	Extron	CMP-103	Operational	Water Damage / Rusty	Replace
6	Crestron	TPMC-CH-IMC	Operational	Unit working during inspection	Replace
7	Panasonic	PT-RW330U	Operational	Water Damage	Replace
8	Extron	CMP-104	Operational	Unit working during inspection	Replace
9	Sennheiser	SZI 1015-TW	Operational	Unit working during inspection	Replace
10	Speakers (Qty 9)	N/A	Operational	Unit working during inspection	Replace
11	Extron	TLM 100T	Operational	Unit working during inspection	Replace
12	Crestron	TPMC-CH-IMC	Operational	Unit working during inspection	Replace
13	Crestron	CNX-RMC	Operational	Unit working during inspection	Replace
14	Extron	SW4RGBHV A	Operational	Unit working during inspection	Replace
15	iPad	MC769LL/A	Operational	Unit working during inspection	Replace

Courtroom 3C & D Rack EQUIPMENT LIST

#	Brand	Model #	Serial #	Description
1	Sennheiser	SI 1015	105774	Wideband Modulator
2	Extron	SW6 RGBHV A	A0HKC6R E24043	Six Input RGBHV Switcher
3	Extron	DA6RGBHV	913964005 E15712	Six Output Wideband RGBHV Distribution Amplifier
4	Middle Atlantic	MW-10FT-FC	N/A	10" Fan Mount with Fan Control
5	Middle Atlantic	MRK-4431	N/A	MRK Series Rack, 44 RU, 31" D
6	Middle Atlantic (Qty 2)	PD-615C-NS	N/A	6 Outlet, Single15 Amp Circuit Power Strip
7	Middle Atlantic	SPN-44-312	N/A	Side Panels, 44 RU, 31-32"D Racks
8	Crestron	AV2	1779150	Economical Dual Bus Control System
9	Shure	SCM820	20I117207	Digital IntelliMix Automatic Mixer
10	Symnet	8X8 DSP	8008X886A0236	DSP Digital Signal Processor
11	Shure	SCM820	2PD0663348	Digital IntelliMix Automatic Mixer
12	SurgeX	SX2120	785555	Rackmountable 20-amp Surge Suppressor/Power Conditioner with 15 Outlets
13	Apple	A1392	C86Q83Z5DV2R	AirPort Express 802.11n (2nd Generation)
14	Tyco	10012 AC-2A	N/A	Paging System
15	Sennheiser	SI 1015	104804	Wideband Modulator
16	Extron	SW6 RGBHV A	891000006 E15251	Six-Input RGBHV Switcher
17	Extron	DA6RGBHV	913964021 E15712	Six Output Wideband RGBHV Distribution Amplifier
18	Middle Atlantic	4715MS-12T-B10	N/A	Rackmount Fan Assembly with Two Cooling Fans
19	QSC	CX302V	90553920	2-Channel 70V Power Amplifier
20	QSC	CX108V	110550156	8-Channel 70V Power Amplifier
21	Crestron	C2N-HBLOCK	6001923 1659355	Multi-type Cresnet Distribution Block

VISUAL INSPECTION

#	Brand	Model #	Serial #	Description
1	Sennheiser	SI 1015	105774	Visible water damage in/around the component
2	Extron	SW6 RGBHV A	A0HKC6R E24043	Visible water damage in/around the component
3	Extron	DA6RGBHV	913964005 E15712	Visible water damage in/around the component
4	Middle Atlantic	MW-10FT-FC	N/A	Visible water damage in/around the component
5	Middle Atlantic	MRK-4431	N/A	Visible water damage in/around the component
6	Middle Atlantic (Qty 2)	PD-615C-NS	N/A	Visible water damage in/around the component
7	Middle Atlantic	SPN-44-312	N/A	Visible water damage in/around the component
8	Crestron	AV2	1779150	Visible water damage in/around the component
9	Shure	SCM820	20I117207	Visible water damage in/around the component
10	Symnet	8X8 DSP	8008X886A0236	Visible water damage in/around the component
11	Shure	SCM820	2PD0663348	Visible water damage in/around the component
12	SurgeX	SX2120	785555	Visible water damage in/around the component
13	Apple	A1392	C86Q83Z5DV2R	Visible water damage in/around the component
14	Tyco	10012 AC-2A	N/A	Visible water damage in/around the component
15	Sennheiser	SI 1015	104804	Visible water damage in/around the component
16	Extron	SW6 RGBHV A	891000006 E15251	Visible water damage in/around the component
17	Extron	DA6RGBHV	913964021 E15712	Visible water damage in/around the component
18	Middle Atlantic	4715MS-12T-B10	N/A	Visible water damage in/around the component
19	QSC	CX302V	90553920	Visible water damage in/around the component
20	QSC	CX108V	110550156	Visible water damage in/around the component
21	Crestron	C2N-HBLOCK	6001923 1659355	Visible water damage in/around the component

PERFORMANCE

#	Brand	Model #	Status	Description	Recommendation
1	Sennheiser	SI 1015	Operational	Unit working during inspection	Replace
2	Extron	SW6 RGBHV A	Operational	Unit working during inspection	Replace
3	Extron	DA6RGBHV	Operational	Unit working during inspection	Replace
4	Middle Atlantic	MW-10FT-FC	Operational	Unit working during inspection	Replace
5	Middle Atlantic	MRK-4431	Operational	Unit working during inspection	Replace
6	Middle Atlantic (Qty 2)	PD-615C-NS	Operational	Unit working during inspection	Replace
7	Middle Atlantic	SPN-44-312	Operational	Unit working during inspection	Replace
8	Crestron	AV2	Operational	Unit working during inspection	Replace
9	Shure	SCM820	Operational	Unit working during inspection	Replace
10	Symnet	8X8 DSP	Operational	Unit working during inspection	Replace
11	Shure	SCM820	Operational	Unit working during inspection	Replace
12	SurgeX	SX2120	Operational	Unit working during inspection	Replace
13	Apple	A1392	Operational	Unit working during inspection	Replace
14	Tyco	10012 AC-2A	Operational	Unit working during inspection	Replace
15	Sennheiser	SI 1015	Operational	Unit working during inspection	Replace
16	Extron	SW6 RGBHV A	Operational	Unit working during inspection	Replace
17	Extron	DA6RGBHV	Operational	Unit working during inspection	Replace
18	Middle Atlantic	4715MS-12T-B10	Operational	Unit working during inspection	Replace
19	QSC	CX302V	Operational	Unit working during inspection	Replace
20	QSC	CX108V	Operational	Unit working during inspection	Replace
21	Crestron	C2N-HBLOCK	Operational	Unit working during inspection	Replace

Courtroom 3D EQUIPMENT LIST					
#	Brand	Model #	Serial #	Description	
1	Extron	CMP-104	N/A	Three-Gang AV Connectivity Mounting Frame	
2	Apple	MC769LL/A	F5RKQX4YDFHW	Microflex® Standard Gooseneck Microphone	
3	Shure (Qty 5)	MX4180/C	N/A	Three-Gang AV Connectivity Mounting Frame	
4	Extron	CMP-103	N/A	Three-Gang AV Connectivity Mounting Frame	
5	Extron	CMP-103	N/A	Apple iPad 2 MC769LL/A Tablet	
6	Crestron	TPMC-CH-IMC	6002771 1767150	LED/ Laser 1-chip DLP, 3500 lumens, WXGA	
7	Panasonic	PT-RW330U	DE6210117	70V Commercial Ceiling Speaker	
8	Speakers (Qty 9)	N/A	N/A	Radiator With Integrated Modulator	
9	Sennheiser	N/A	N/A	Three-Gang AV Connectivity Mounting Frame	
10	Extron	CMP-104	N/A	Secure Mounting Enclosure for iPad	
11	Extron	TLM-100T	N/A	Balanced AV Interface Module for TPS--12	
12	Crestron	TPMC-CH-IMC	6002771 1687913	Balanced AV Interface Module for TPS--12	
13	Crestron	CNX-RMC	6001328 2066713	Video Receiver and Control Interface	
14	Extron	SW4RGBHV A	861278024 E15727	Four-Input RGBHV Switcher	
15	Sony	SLV-D370P	625524	Apple iPad 2 MC769LL/A Tablet	
VISUAL INSPECTION					
#	Brand	Model #	Serial #	Description	
1	Extron	CMP-104	N/A	No visible noticeable damage to report	
2	Apple	MC769LL/A	F5RKQX4YDFHW	No visible noticeable damage to report	
3	Shure (Qty 5)	MX4180/C	N/A	No visible noticeable damage to report	
4	Extron	CMP-103	N/A	No visible noticeable damage to report	
5	Extron	CMP-103	N/A	No visible noticeable damage to report	
6	Crestron	TPMC-CH-IMC	6002771 1767150	No visible noticeable damage to report	
7	Panasonic	PT-RW330U	DE6210117	No visible noticeable damage to report	
8	Speakers (Qty 9)	N/A	N/A	No visible noticeable damage to report	
9	Sennheiser	N/A	N/A	No visible noticeable damage to report	
10	Extron	CMP-104	N/A	No visible noticeable damage to report	
11	Extron	TLM-100T	N/A	No visible noticeable damage to report	
12	Crestron	TPMC-CH-IMC	6002771 1687913	No visible noticeable damage to report	
13	Crestron	CNX-RMC	6001328 2066713	No visible noticeable damage to report	
14	Extron	SW4RGBHV A	861278024 E15727	No visible noticeable damage to report	
15	Sony	SLV-D370P	625524	No visible noticeable damage to report	
PERFORMANCE					
#	Brand	Model #	Status	Description	Recommendation
1	Extron	CMP-104	Operational	No apparent issues	Good
2	Apple	MC769LL/A	Operational	No apparent issues	Good
3	Shure (Qty 5)	MX4180/C	Operational	No apparent issues	Good
4	Extron	CMP-103	Operational	No apparent issues	Good
5	Extron	CMP-103	Operational	No apparent issues	Good
6	Crestron	TPMC-CH-IMC	Operational	No apparent issues	Good
7	Panasonic	PT-RW330U	Operational	No apparent issues	Good
8	Speakers (Qty 9)	N/A	Operational	No apparent issues	Good
9	Sennheiser	N/A	Operational	No apparent issues	Good
10	Extron	CMP-104	Operational	No apparent issues	Good
11	Extron	TLM-100T	Operational	No apparent issues	Good
12	Crestron	TPMC-CH-IMC	Operational	No apparent issues	Good
13	Crestron	CNX-RMC	Operational	No apparent issues	Good
14	Extron	SW4RGBHV A	Operational	No apparent issues	Good
15	Sony	SLV-D370P	Operational	No apparent issues	Good

Recommendations

Exposure of any type of wire or cable product to water will inevitably impact metallic components (conductor, metallic shield or armor) and is subject to corrosion that will damage the component itself and/or cause termination failures. As a result, it is recommended to completely replace the wiring of the audio-visual (AV) system to avoid future issues such as degradation of signal transmitted by the cabling resulting in interruptions in the daily operations and loss of money due to downtime.

Replacing all AV equipment that has been either been exposed to water directly, or indirectly, via a connection to an AV equipment rack that endured water exposure is recommended. Water damage leads to oxidation, corrosion and degradation of the electronic components.

The existing AV equipment is more than 10 years old and mostly obsolete and incompatible with current industry standards of AV. Finding exact replacements of hardware is nearly impossible as almost all equipment housed in the audio-visual racks are either end of life or obsolete. It is recommended to replace the obsolete equipment with similar/comparable hardware to meet current US industry AV standards.

During our assessment walkthrough we noticed audio distortion coming from speakers in multiple rooms which is a potential sign of water damage beginning to be an issue for the overall AV system.